



Technical Bulletin

NISSAN NORTH AMERICA, INC.
Copyright ©

SERVICE BULLETIN

Classification: EL03-034	Reference: NTB03-087	Date: October 1, 2003
-----------------------------	-------------------------	--------------------------

BOSE® AUDIO SYSTEM – SOUND CLARITY

APPLIED VEHICLE: 2003 350Z (Z33), equipped with Bose® audio system

APPLIED VINS: Vehicles built in the following ranges:
JN1ZA34E83T005616 - JN1AZ34E03T021338
JN1ZA34D63T104720 - JN1AZ34D33T119707

APPLIED DATES: Vehicles built from September 27, 2002 to June 10, 2003

IF YOU CONFIRM:

The treble lacks "clarity" (clear tones).

ACTION:

Check the part number on the Audio Amplifier. Refer to the **Audio Amplifier Part Number Check Procedure** (page 2).

- If the part number is **28060-CE400**, this bulletin does NOT apply.
- If the part number is **NOT 28060-CE400**, replace the Audio Amplifier. Refer to the **Audio Amplifier Replacement Procedure** (page 9).




Figure 1